MACT Training Subpart WWWW – Reinforced Plastic Composites

Melissa Woolf 2/23/05


Overview

- Pretest
- Industry Overview
- Applicability
- Compliance Requirements
- NE facilities
- Post-test



Industry Overview

- Composite combination of materials each made of distinct & different properties
- Thermosetting polymer resins and reinforcement fibers
 - Usually glass fibers could be graphite or other
 - Thermoset can not be softened by heating



Industry Overview Open Molding Most common Resins, reinforcement, and other materials applied by hand or sprayed Gel coat applied to mold – appearance, color, & weather resistance Glass (resin) sprayed on mold (reinforcement) Mold left open while cured Product removed from mold





































	Industry Overview
r Em	issions
•	Tainly Styrene & MMA
• 5	ome MEK, xylene, & cobalt
• (Cleaning solvents may have HAPs
• A	cetone used a lot – but not a HAP or VOC
• P	articulates from trimming & sanding
	table used for open molding
	lot all emissions evaporated



MACT Applicability



- Major sources (HAP PTE >10 & 25)
- Reinforced or non-reinforced plastic composites manufacturer
- Uses thermoset resins and/or gel coats that contain styrene

MACT Applicability

- Exempt
 - Area source
 - Only repairs reinforced plastic composites
 - Research & Development
 - Use <1.2 tpy of resins & gel coats that contain styrene

MACT Applicability Fiberglass boats or boat parts If all composites used in boats Subject to Subpart VVVV If have both Those not used in manufacture of boats – comply with this rule Could have all operations subject to Boat MACT, if emissions would not increase

MACT Applicability

- New source
 - Construction/reconstruction commenced after 8/2/01
 - AND no other reinforced plastics composites existed at site when construction commenced
- Existing everything that isn't new!

Compliance Requirements

- Emission Limits, HAP content limits, or emission reduction
- Work practices
- Recordkeeping
- Reporting



Emission Limits New source emitting <100 tpy of HAPs Existing Emit <100 tpy from centrifugal casting a continuous lamination Or don't have those operations

Emission Limits

- New emit ≥ 100 tpy of HAPs
- Existing emit ≥ 100 tpy from centrifugal casting & continuous lamination
 - 95% reduction of emissions
 - Also, meet emission limits for other operations

Large Parts Exemption



- New Sources subject to 95% control
 - Meet emission limits in Table 3 of rule
 - Open molding part >250 cubic feet or 50 square feet on one side
 - Large pultruded part >24 inches outside perimeter, or 350 or more reinforcements

Large Parts Exemption Existing pultrusion operations Substitute "air flow management" for 60% emission reduction Cross sectional area of 60 inches or more and 1,000 or more reinforcements

Work Practice Requirements


- All operations must meet specific work practice standards
 - E.g. No HAP cleaning solvents except styrene in closed system & used to clean cured resin from guns
 - Keep containers that store HAPs closed or covered except when adding or removing materials
 - See Table 2 on EPA brochure



Compliance Dates Sources that emit <100 tpy but increase to >100 tpy, Comply 3 years from the compliance report listing exceedence Sources can exceed 100 tpy once in calendar year One time exemption

Notify permitting authority

Determining HAP Emissions Existing Initial calculation with data 12 months prior to 4/21/03 Calculate again with data 12 months prior to compliance date New Projected emissions for the 12 months following startup






Open Molding & Centrifugal Casting

- Meet individual HAP emission limits for each operation
- Meet HAP emission limits as weighted average
- - See Table 3 of rule for %
- If several types of operations, can meet emission limit for one & use same resin for all operations

Continuous Lamination/Casting

- Demonstrate each line meets standard
- Average across lines
- Add-on controls 58.5% emission reduction
- Add-on controls capture all wet-out area emissions in permanent enclosure & vent to 95% efficient control device
- Use combination





Emission limits HAP content of material - MSDS Monthly consumption rates Operations that use HAP-containing materials Calculate 12-month rolling totals within 30 days Can use purchase records If materials compliant – don't need to track monthly usage

Averaging provisions HAP content in products used for each operation Amount used in each operation Monthly calculations Purchase records can be used 10 54 12 10

Add-on Controls

- Subpart SS
- Performance test every five years
- Monitor operating parameters from test
- If using enclosure provision
 - Conduct design evaluation
- Can use continuous emission monitors

Recordkeeping

- Copy of each notification & report
- Performance test records
- All data used to demonstrate compliance
- Certified statement that they are in compliance with the work practice requirements

Recordkeeping

- Continuous casting/lamination documentation of emission factor rationale
- Add-on controls
 - Startup, Shutdown, & Malfunction (SSM)Plan
 - All records to show compliance with Subpart SS
- Records maintained 5 years

Notifications

- Initial notification
 - Existing 8/19/03
 - New 120 days after startup
- Notification of performance test
 - If using add-on control
 - 60 days prior to testing

Notifications

- Compliance status
 - Compliant coatings, equipment requirements, anything other than averaging
 - 30 days after compliance date
 - Emission limit averaging
 - One year plus 30 days after compliance date

•			

